42-008-00000



United States Steel Corporation Clairton Works 400 State Street Clairton, PA 15025

978 = 00 (00 Tice of outrage) 4/19/02 (1)

April 19, 2002

Dr. Roger C. Westman Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: Michael Ioff (3AT23)

Assistant Council Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745 ATTN: Ward Kelsey, Esq.

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: USS Reference Number: 02-0046

#2 Control Room USS Clairton Works

Gentlemen:

The attached form terminates the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

R. R. Terza General Manager

Clairton Works Raw Materials

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

- USS Reference Number: 02-0046 Termination 1.
- 2. Date & Time of Breakdown: Date: 04/14/00 Time: 1650 hours
- 3. Company Name: U.S. Steel Corporation - USS Clairton Works
- Specific Equipment Involved or Affected: #2 Control Room 4.
- BAPC Permit Number (if applicable): 5.
- 6. Location: Clairton, PA
- Nature and cause of breakdown: The Light Oil regenerators were 7. removed from service to repair an expansion joint in the 30" sub2 gas line.
- Identification of Emissions: 8.
 - Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.) Α. Elevated H2S in the downriver gas line system, causing increased SO2 and VOC at point of combustion.
 - В. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). SO2 is an eye, nose, and throat irritant.
 - Amount of each type emitted (or likely to be emitted). C. Light to moderate
- Measures taken (or to be taken) to minimize length of breakdown 9. and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so). The Light Oil Regenerators were returned to service upon completion of the repairs.

Facility back in operation - Date: 04/18/02 Time: 2315 hours 10.

signature Cleso m. Davis Date 4/19/02 Coleen M. Davis

Environmental Control Engineer Phone: 233-1015